		Rank of			
	Time of first	Time of fire	Location - Town /	Investigating	Number of
Date	call	service arrival	Village	Officer	fatalities
8th Mar 2018	11:05:36	11:13:58	Christchurch	Station Manager	1
4011.84					
10th Mar 2018	14:45:54	15:00:57	Poole	Station Manager	1
2018	14.45.54	15.00.57	Poole	Station Manager	1
30th Oct 2018	18:04:41	18:27:49	Somerford	Station Manager	1
11th Dec 2018	15:59:39	16:07:20	Swindon	Group Manager	1
24.1.5	44.56.46	45.07.44	na di di		
21st Dec 2018	14:56:46	15:07:44	Melksham	Group Manager	1
3rd Feb 2019	23:34:39	23:38:57	Bournemouth	Station Manager	1
3.4.65.2013	23.3 1.33	23.33.37	Boarnemoath	Station Wanager	_
31st Aug 2019	23:17:20	23:24:23	Poole	Station Manager	1
22nd Jan 2020	02:55:49	03:04:49	Weymouth	Station Manager	1
9th Feb 2020	22:46:57	22:57:23	Dorchester	Station Manager	1
3111 65 2020	22.10.37	22.37.23	Dorenester	Station Wanager	
27th Mar					
2020	20:17:15	20:23:56	Poole	Station Manager	1
0.1 6	22.44.64	22.50.66			[_
9th Sept 2020	23:44:04	23:59:29	Shroton	Group Manager	1

40th to 2024	22.40.40	22 57 20	Chaft and	Classic Adams and	
10th Jan 2021	23:49:19	23:57:39	Shaftesbury	Station Manager	1
7th Feb 2021	10:11:46	10:19:50	Swindon	Group Manager	1
31st Mar 2021	10:53:35	11:03:39	Holten Heath	Station Manager	1
5th Sept 2021	02:21:09	02:29:04	Swindon	Group Manager	1
6th Nov 2021	16:32:19	16:38:48	Poole	Station Manager	1
20th Mar					
2022	16:57:50	17:04:01	Swindon	Station Manager	1

17th Jul 2022	04:24:01	04:37:30	Blandford	Station Manager	1
			_	_	_
27th Sept					
2022	04:21:02	04:29:00	Weymouth	Station Manager	1

	Skin burns witnessed Yes/No	Flashover Yes/No	Flashover suporting evidence
rige/ 5 of fatalities	Withessed Tesy No	1103110101 103/110	CVIGENCE
86	Yes	No	N/A
66	Yes	No	N/A
59	Yes	No	N/A
76	Yes	No	N/A
48	Yes	No	N/A
75	Yes	No	N/A
88	Yes	No	N/A
70	Yes	No	N/A
			,
59	Yes	No	N/A
69	Yes	No	NI/A
09	res	No	N/A
67	Yes	No	N/A

89	Yes	No	N/A
1.0			Post fire
42	Yes	Yes in room of origin	investigation
			Total loss of
57	Yes	Yes	structure
66	Yes	Yes	Photos in report
81	Yes	No	N/A
73	Yes	No	N/A
/3	163	INU	N/A

			Total loss of
39	Yes	Yes	structure
F4	Wa a	NI -	Fine investigation
51	Yes	No	Fire investigation

		Recorded cause of
Property type	Property construction	death
Terraced house - Building/Dwelling/House - single	Traditional brick &	et la ta d
occupancy	timber	Fire related
Purpose built block of flats -		
Building/Dwelling/Purpose Built Flat/Maisonette	Duial. E ataua	Cine melete d
multiple occupancy/4 to 9 storeys	Brick - 5 storeys Traditional brick &	Fire related
End terrace bungalow - Building/Dwelling/Bungalow -		Fire related / Ones
single occupancy	timber with tiled roof	Fire related / Open
 Link-terraced bungalow - Building/Dwelling/Bungalow -		
single occupancy	Standard construction	Fire related
Single decapancy		
Self contained flat - Building/Dwelling/Purpose Built		
Flat/Maisonette - multiple occupancy/Up to 3 storeys	Brick	Fire related
Purpose built flats - Sheltered housing -		
Building/Dwelling/Purpose Built Flat/Maisonette -	Brick / Block / Pitched	
multiple occupancy/Up to 3 storeys	tiled roof	Fire related
Detached bungalow - Building/Dwelling/Bungalow -		
single occupancy	Brick - 1960's	Fire related
Licensed house of multiple occupancy -		
Building/Dwelling/Converted Flat/Maisonette -	Traditional construction	
multiple occupancy/3 or more storeys	of brick, wood and slate	Fire related
Terraced house sub-divided into flats -		
Building/Dwelling/Converted Flat/Maisonette -	Traditional construction	
multiple occupancy/Up to 2 storeys	of brick, wood and slate	Fire related
End terraced house sub-divided into flats -		
Building/Dwelling/Converted Flat/Maisonette -	Traditional construction	
multiple occupancy/Up to 2 storeys	of brick, wood and tiles	Fire related
Bungalow - Building/Dwelling/Bungalow - single		
occupancy	Traditional brick	Fire related

	Ι	
	Concrete frame, brick	
Purpose built sheltered housing / retirement complex -	infill, weatherboard	
Building/Other Residential/Residential	façade, gabled roof with	
Home/Retirement/Elderly	concrete tiles.	Fire related
The man and a state of the stat	00.101.000.01001	
Purpose built block of flats -		
Building/Dwelling/Purpose Built Flat/Maisonette -	Brick and tiled roof - 2	
multiple occupancy/Up to 3 storeys	storey	Fire related
	,	
Touring Caravan - Building/Dwelling/caravan/mobile		
home (permanent dwelling)	Un-Known	Fire related
Terraced house - Building/Dwelling/House - single	Brick and render with	
occupancy	tiled roof	Awaiting verdict
Purpose built block of flats -		
Building/Dwelling/Purpose Built Flat/Maisonette -	Brick, block and render	
multiple occupancy/4 to 9 storeys	with pitched tiled roofs	Fire related
Purpose built flats for sheltered accommodation -	Brick elevations with	
Building/Dwelling/Self contained Sheltered Housing	flat roof	Fire related

Caravan - Property - Road Vehicle - Caravan		
	Un-known	Awaiting vardict
unspecified	UII-KIIUWII	Awaiting verdict
Semi-detached house - Building/Dwelling/House -	Brick & block rendered	
single occupancy	elevations and tiled roof	Awaiting verdict

Location of fatality /			
casualty	Seat of fire, location	Source of ignition	Material first ignited
Different room, cabin or			
compartment of origin		Smoking related -	Furniture/Furnishings -
on floor	Lounge	Smoking materials	Upholstered furniture
Room, cabin or		Smoking related -	
compartment of origin	Living room	Smoking materials	Other
Room, cabin or		Smoking related -	Clothing/Textiles -
compartment of origin	Bedroom	Smoking materials	Other textiles
Room, cabin or		Smoking related -	Clothing/Textiles -
compartment of origin	Living room	Smoking materials	Other textiles
		Naked flame - lighted	
Room, cabin or		paper or card, or other	Clothing/Textiles -
compartment of origin	Living room	naked flame	Other textiles
Room, cabin or		Smoking related -	Clothing/Textiles -
compartment of origin	Bathroom/Toilet	Smoking materials	Clothing
Room, cabin or		Smoking related -	Clothing/Textiles -
compartment of origin	Living room	Smoking materials	Clothing
Outside building,		Smoking related -	Clothing/Textiles -
vehicle etc of origin	Living room	Smoking materials	Clothing
Room, cabin or		Heating equipment -	Clothing/Textiles -
compartment of origin	Living room	Heating/Fire	Clothing
Different room, cabin or			
compartment on floor			
of origin	Bedroom	Not known	Not known
Different room, cabin or			
compartment on floor		Smoking related -	
of origin	Living room	Smoking materials	Not known

	T	T	T
Room, cabin or		Smoking related -	Furniture/Furnishings -
compartment of origin	Bedsitting room	Smoking materials	Upholstered furniture
compartment of origin	bedsitting room	Silloking materials	opnoistered furniture
Room, cabin or			
compartment of origin	Living room	See cause recorded (X)	See cause recorded (X)
		, ,	, ,
Room, cabin or			
compartment of origin	Not known	Not known	Not known
Room, cabin or		Cooking appliance -	
compartment of origin	Kitchen	Cooker incl. oven	Food - Cooking oil or fat
Different room, cabin or			
compartment on floor		Smoking related -	Clothing/Textiles -
of origin	Bedroom	Smoking materials	Clothing
Different versus saleitus			
Different room, cabin or		Natabas and sondi-	Clathing/Taytiles
compartment on floor	Dodroom	Matches and candles -	Clothing/Textiles -
of origin	Bedroom	Candles	Clothing

Room, cabin or compartment of origin	Other inside/Cargo area	Not Known	Not Known
23	z menere, em go ureu		
	l	Smoking related -	Furniture/Furnishings -
Floor above origin	Living room	Smoking materials	Upholstered furniture

Material primarily		Extent of fire spread
responsible for fire	Extent of fire beyond	beyond the room of
development	first item ignited	origin
	ge	
Furniture/Furnishings -		
Upholstered furniture	Whole Building	Whole Building
oprioistered ranneare	Trible Lamaning	
Clothing/Textiles -	Limited to room of	Limited to room of
Other textiles	origin	origin
Furniture/Furnishings -	Limited to room of	Limited to room of
Bed/Mattress	origin	origin
2007	Limited to floor of	Limited to floor of
Clothing/Textiles -	Origin (not whole	Origin (not whole
Other textiles	building)	building)
Other textiles	bulluling)	bulluling)
	Limited to room of	Limited to room of
None		
None	origin	origin
	Limited to room of	Limited to room of
None		
None	origin	origin
Clathing/Toytiles	Limited to room of	Limited to room of
Clothing/Textiles -	Limited to room of	
Clothing	origin	origin
Clathing/Toytiles	Limited to item 1st	Limited to item 1st
Clothing/Textiles -		
Clothing	ignited	ignited
Clathing/Toytiles	Limited to it one 1 of	limited to itom 1st
Clothing/Textiles -	Limited to item 1st	Limited to item 1st
Clothing	ignited	ignited
	Literatura de la compansión	Carlo de la caración de
	Limited to room of	Limited to room of
Not known	origin	origin
	Limited to floor of	Limited to floor of
	Origin (not whole	Origin (not whole
Not known	building)	building)

Furniture/Furnishings -	Limited to room of	Limited to room of
Upholstered furniture	origin	origin
	- 0	- 0
	Limited to floor of	Limited to floor of
	Origin (not whole	Origin (not whole
Not known	building)	building)
	<u> </u>	<u> </u>
Not known	Whole building	Whole building
Structual/Fixtures/Fittin		
gs - Internal - Internal		
fittings	Whole Building	Whole Building
Clothing/Textiles -	Limited to item 1st	Limited to item 1st
Clothing	ignited	ignited
	Limited to item 1st	Limited to item 1st
None	ignited	ignited

Furniture/Furnishings - Upholstered furniture			
Upholstered furniture whole building) whole building)	Upholstered furniture Furniture/Furnishings -	Limited to 2 floors (not	Limited to 2 floors (not

Considered opinion as to the most likely cause of fire recorded by fire service.

Accidental ignition by discarded smoking materials

Cigarette coming into contact with combustible materials

Accidental ignition of bedding textiles by discarded smoking materials

Smoking material (cigar) coming into contact with flammable materials (clothes/blanket) draped on armchair.

Ignition of the deceased clothing with a naked flame, most likely the cigarette lighter located near the body.

Accidental ignition of clothing by a discarded cigarette or match, resulting in flaming combustion of clothing.

Accidental ignition of clothing by a cigarette, resulting in flaming combustion of clothing.

The accidental ignition of clothing with smoking materials.

The accidental ignition of clothing when in contact with a naked flame produced by a gas fire

Accidental ignition of bedding and mattress by discarded smoking materials.

The most probable cause of this incident is the ignition of flammable vapour given off during localised heating and the pyrolysis of materials commonly used for the construction of a sofa bed and /or associated soft furnishings. Due to the nature of the damage, I am unable to confirm whether this was a deliberate act or an accidental ignition,or whether smoking materials carelessly dropped down the back of the sofa caused the initial pyrolysis of combustible materials and was the most probable ignition source ofthe flammable vapour.

Accidental ignition of clothing and blankets by a discarded cigarette or unextinguished'zippo'lighter,resulting in flaming combustion of clothing and blankets possibly acceleratedby the presence of residuebuild up from the continued use of an emollient.

It is the considered opinion that the most likely cause was a fire of deliberate ignition involving combustible materials in the form of bedding and an ignition source such as a lighter, cigarette or candle.

The exact origin of the fire is unknown due to the extent of damage. There is no physical evidence to determine whether ignition was deliberate, by self, or accidental. There is no evidence to support deliberate ignition by other person.

Accidental due to unattended cooking or omitting to fully turn off gas hob following cookingcausing panor griddleand/orcombustiblesinsurrounding area to heat up and igniteand spread to wall cabinet directly above.

Accidental ignition of combustible items coming in to contact with a lit cigarette lighter Whilst ironing accidental ignition of a dress which appeared to be made of Kente cloth by a lit candle placed on the floor directly below the ironing board.

The exact origin of the fire within the caravan could not be determined due to the extensive damage, both to XXXXXXX and the caravan. No physical evidence remained to support deliberate or accidental ignition by self or other person(s). Due to the extensive damage, it was also not possible to determine accidental ignition by faulty electrical appliance. Due to the damage and absence of physical evidence I am unable to give a most likely cause, however I cannot discount ignition by a faulty electrical appliance or ignition by XXXXXXXX with unknown intent.

Accidental or negligent disposal of smoking materials