



**Time of Call:** 01/01/2018 20:02:05  
**Type:** Fire - Primary  
**Last Updated:** 14/03/2018 22:50:52  
**Initial Incident Type:** F11.1 Smell of Burning  
**Initial Address:** \*\*\*\*\*

## Incident Identification

<b>FRS Incident Number</b>	TT022104-01012018
<b>Recording FRS</b>	Dorset & Wiltshire
<b>'Over the border' incident</b>	No

## Incident Details at Call

<b>Origin of call</b>	Person (land line)
<b>Incident type at call</b>	Fire - Fire
<b>Time of call</b>	01/01/2018 20:02:05
<b>Late call</b>	No
<b>Date/time of stopped message</b>	01/01/2018 21:08:13
<b>Date/time closed</b>	01/01/2018 21:08:14

## Incident Details On Attendance

<b>Incident Category</b>	Fire
<b>Type of property</b>	Property > Building > Non Residential > Retail > Single shop
<b>Property Regulated</b>	Yes
<b>Number of appliances deployed</b>	8
<b>Victims involved</b>	No
<b>Evacuation involved</b>	Yes
<b>Attack on firefighters</b>	No
<b>Derelict building involved</b>	No
<b>Chimney fire</b>	No

## On Attendance - Incident Location

<b>Town</b>	POOLE
<b>Postcode</b>	BH15 1
<b>X-coordinates</b>	401***
<b>Y-coordinates</b>	090***

## On Attendance - Additional Info

<b>Multiple seats</b>	No
<b>Time between ignition and discovery</b>	Immediately
<b>Time between discovery and call</b>	Immediately
<b>How the fire was discovered</b>	Person

<b>Cause/motive</b>	Accidental
<b>Occupied at time of incident</b>	Yes
<b>Building normally occupied</b>	Yes - occupied
<b>State of building means of escape</b>	OK - no visible concerns
<b>State of buildings compartmentation found</b>	Stopped/Checked spread
<b>Alarm systems</b>	<b>Alarm system type:</b> Mains security system including smoke alarm <b>Location:</b> In room of origin of fire <b>Operated:</b> No <b>Reason for poor outcome:</b> Alerted by other means
<b>Were Hazardous materials involved</b>	No

## On Attendance - Resources Used

<b>FRS Vehicles</b>	<b>FRS Vehicle Type:</b>	Pumping - Water tender ladder
	<b>Number of crew:</b>	5
	<b>Demounted resource:</b>	No
	<b>Time mobile:</b>	01/01/2018 20:05:01
	<b>Time at scene:</b>	01/01/2018 20:14:40
	<b>Time available:</b>	01/01/2018 20:30:05
	<b>Deployed from:</b>	Home Station
	<b>FRS:</b>	Dorset & Wiltshire
	<b>Station:</b>	Westbourne fire station
	<b>FRS Vehicle Type:</b>	Pumping - Water tender ladder
	<b>Number of crew:</b>	5
	<b>Demounted resource:</b>	No
	<b>Time mobile:</b>	01/01/2018 20:05:01
<b>Time at scene:</b>	01/01/2018 20:17:23	
<b>Time available:</b>	01/01/2018 20:29:14	
<b>Deployed from:</b>	Home Station	
<b>FRS:</b>	Dorset & Wiltshire	
<b>Station:</b>	Springbourne fire station	
<b>FRS Vehicle Type:</b>	Aerial - Aerial ladder platform	
<b>Number of crew:</b>	2	
<b>Demounted resource:</b>	No	
<b>Time mobile:</b>	01/01/2018 20:05:23	
<b>Time at scene:</b>	01/01/2018 20:15:14	
<b>Time available:</b>	01/01/2018 20:30:25	
<b>Deployed from:</b>	Home Station	
<b>FRS:</b>	Dorset & Wiltshire	
<b>Station:</b>	Westbourne fire station	
<b>FRS Vehicle Type:</b>	Pumping - Water tender ladder	
<b>Number of crew:</b>	5	
<b>Demounted resource:</b>	No	
<b>Time mobile:</b>	01/01/2018 20:05:27	
<b>Time at scene:</b>	01/01/2018 20:18:58	
<b>Time available:</b>	01/01/2018 20:29:52	
<b>Deployed from:</b>	Home Station	
<b>FRS:</b>	Dorset & Wiltshire	
<b>Station:</b>	Redhill fire station	

**FRS Vehicle Type:** Pumping - Water tender ladder  
**Number of crew:** 5  
**Demounted resource:** No  
**Time mobile:** 01/01/2018 20:08:06  
**Time at scene:** 01/01/2018 20:21:26  
**Time available:** 01/01/2018 20:27:29  
**Deployed from:** Home Station  
**FRS:** Dorset & Wiltshire  
**Station:** Wimborne fire station

---

**FRS Vehicle Type:** Pumping - Water tender ladder  
**Number of crew:** 4  
**Demounted resource:** No  
**Time mobile:** 01/01/2018 20:04:39  
**Time at scene:** 01/01/2018 20:09:12  
**Time available:** 01/01/2018 20:57:41  
**Deployed from:** Home Station  
**FRS:** Dorset & Wiltshire  
**Station:** Poole fire station

---

**FRS Vehicle Type:** Pumping - Water tender ladder  
**Number of crew:** 5  
**Demounted resource:** No  
**Time mobile:** 01/01/2018 20:05:13  
**Time at scene:** 01/01/2018 20:40:16  
**Time available:** 01/01/2018 20:47:09  
**Deployed from:** Home Station  
**FRS:** Dorset & Wiltshire  
**Station:** Poole fire station

---

**FRS Vehicle Type:** Pumping - Water tender ladder  
**Number of crew:** 5  
**Demounted resource:** No  
**Time mobile:** 01/01/2018 20:09:49  
**Time at scene:** 01/01/2018 20:13:36  
**Time available:** 01/01/2018 20:30:08  
**Deployed from:** Home Station  
**FRS:** Dorset & Wiltshire  
**Station:** Poole fire station

---

**FRS Vehicle Type:** Pumping - Water tender ladder  
**Number of crew:** 5  
**Demounted resource:** No  
**Time mobile:** 01/01/2018 20:09:23  
**Time at scene:** 01/01/2018 20:11:39  
**Time available:** 01/01/2018 20:30:01  
**Deployed from:** Home Station  
**FRS:** Dorset & Wiltshire  
**Station:** Hamworthy fire station

---

**FRS Vehicle Type:** Command - Control unit  
**Number of crew:** 2  
**Demounted resource:** No  
**Time mobile:** 01/01/2018 20:12:12  
**Time at scene:** 01/01/2018 20:26:03  
**Time available:** 01/01/2018 20:30:09  
**Deployed from:** Home Station  
**FRS:** Dorset & Wiltshire  
**Station:** Hamworthy fire station

---

**FRS Vehicle Type:** Transport - Officer's car  
**Number of crew:** 1  
**Demounted resource:** No  
**Time mobile:** 01/01/2018 20:06:20  
**Time at scene:** 01/01/2018 20:14:01  
**Time available:** 01/01/2018 20:41:02  
**Deployed from:** Home Station  
**FRS:** Dorset & Wiltshire  
**Station:** Westbourne fire station

---

**FRS Vehicle Type:** Transport - Officer's car  
**Number of crew:** 1  
**Demounted resource:** No  
**Time mobile:** 01/01/2018 20:08:31  
**Time at scene:** 01/01/2018 20:20:31  
**Time available:** 01/01/2018 20:58:02  
**Deployed from:** Home Station  
**FRS:** Dorset & Wiltshire  
**Station:** Ferndown fire station

**Equipment**

**Type:** Detection/Location Equipment - Thermal imaging camera  
**Number used:** 2

---

**Type:** Ladders - Short extension  
**Number used:** 1

---

**Type:** Ladders - Triple/Short extension ladder  
**Number used:** 1

**On Attendance - Action**

<b>Delay in commencing firefighting action</b>	No delay
<b>Main action taken by the general public prior to arrival</b>	None
<b>Main action taken by FRS personnel</b>	None - No firefighting

**On Attendance - Damage**

<b>Main cause of fire</b>	Fault in equipment or appliance
<b>Make and model of faulty appliance</b>	unknown
<b>Person or action that caused the fire</b>	Not known
<b>Source of ignition</b>	Other domestic style appliance - Fridge/Freezer
<b>Powered the ignition</b>	Electric
<b>Item that ignited first</b>	Not known
<b>Item mainly responsible for spreading fire</b>	Not known
<b>Rapid fire growth caused by</b>	No rapid fire growth
<b>Dangerous substances involved</b>	None
<b>Explosion</b>	No
<b>Type of room/compartment fire started in</b>	Shop floor/Showroom/Display hall
<b>Factors contributing to start of fire</b>	None
<b>Impairment due to suspected drugs/alcohol</b>	No
<b>Special method of building construction</b>	Cladding
<b>Heat and smoke damage only</b>	Yes
<b>Extent of the fire damage at stop</b>	Up to 5
<b>Extent of the total area damages (sq.m at stop)</b>	Up to 5
<b>Number of floors above ground</b>	11

Number of floors below ground	0
Floor fire originated	1